


**CASE MIDRANGE COMBINE/ 20 SERIES ADAPTER KIT
192025 KIT INSTRUCTIONS**


Bolt on 174216 to combine as shown.



The washer between flange nut and feeder house face plate are replaced with 174216.

On 20 Series combine adapter, replace the gearbox with 153395.

The existing 129473 arm handle assembly will have to be reworked. Drill hole in welded pin to larger size (using $\frac{1}{4}$ " drill bit) to enable lynch pin to be installed.



**CASE MIDRANGE COMBINE/ 20 SERIES ADAPTER KIT
192025 KIT INSTRUCTIONS**

With adapter gearbox/torque arm removed from combine, open combine shield.



If this access for installing corn head driveline is deemed not acceptable then following rework to combine shield is required. The outer shield is made up of the two half shields with one welded to combine. Mark location of shields. Then grind off the two welds securing half shield. Rotate shield 90° counterclockwise and weld shield back on.

